

## CAN YOU IDENTIFY THE HAZARDS?



1. The handrail does not extend far enough. It should extend to the end of the walkway. In its current position, it would be a very long reach from the parking lot to sidewalk and vice versa.
2. The landscape plant is encroaching on the sidewalk walking surface, creating a slip, trip and fall hazard. Walkways should be kept clear and unobstructed, and the plant should be trimmed.
3. The curb is too high from the parking lot to the walkway, creating a trip and fall hazard. This distance should be shorter.
4. The curbing needs to be repainted. This will allow for easier identification to the users that a step up/step down hazard is present.

© 2012 GuideOne Risk Resources for Health Care, a division of Lutheran Trust, Church Asset Management. All rights reserved.

This material is for informational purposes only. It is not intended to give specific legal or risk management advice, nor are any suggested checklists or actions plans intended to include or address all possible risk management exposures or solutions.

You are encouraged to consult with your own attorney or other expert consultants for a professional opinion specific to your situation.